News March 2025





Fuel pump

HÜCO No. 133045 / HITACHI No. 2503045					
	PORSCHE	95562008900			
	PORSCHE	95562008901			
	VW GROUP	1K0906089			
	VW GROUP	1K0906089B			
	VW GROUP	1K0906089C			

Throttle body

PSA 0345E0 VW GROUP 03G128063B FORD 1427361 VW GROUP 03G128063K JAGUAR C2Z15660 VW GROUP 03G128063L	HÜCO No. 139023 / HITAO	CHI No. 2509023		HÜCO No. 139027 / HITA	CHI No. 2509027	
JAGUAR C2Z15660 VW GROUP 03G128063L	FORD	PSA	0345E0		VW GROUP	03G128063B
		1427361		VW GROUP	03G128063K	
		JAGUAR	C2Z15660	-	VW GROUP	03G128063L
LANCIA 9656932580 VW GROUP 03G128063R		9656932580		VW GROUP	03G128063R	
LANDROVER LR001001 MITSUBISHI MN980320		LR001001		MITSUBISHI	MN980320	

Glow plug relay

HÜCO No. 132269 / HITACHI No. 2502269					
replaced 132118 / 2502118	MERCEDES-BENZ	A4159009003			
	MERCEDES-BENZ	A6079000500			
	NISSAN	1106700Q0G			
	OPEL	93168361			
	RENAULT	271206395R			

Shock absorber

TOKICO No. 3165 / HITACHI Order No. 2017849					
	ISUZU	9516306610			
	ISUZU	9516306600			

Hitachi Astemo Aftermarket Germany GmbH Eugen-Gerstenmaier-Str. 8 • 32339 Espelkamp • Germany

Tel: +49 (0) 5772 567 890 E-Mail: emea.af@hitachiastemo.com





Visit our website









Updated Tokico catalogue available.



Check our YouTube Channel for new videos.





OE names for references only. Please check the TecDoc catalogue for a complete application list of all products.

You receive this newsletter based on our business relationship or the fact that you agreed on the service. If you would like to unsubscribe from the newsletter please let us know.